




Add layout note on pins 22 and 28 of MAX8771 controller. These nets have large voltage swings. Need to route them away from the sensitive areas that are trying to detect small changes in voltage, such as the voltage sense VccSense lines.



PROJECT : AT6
Quanta Computer Inc.

Size	Document Number	Rev
Custom	CPU_CORE(MAX8771)	1A
Date:	Monday, May 22, 2006	Sheet 44 of 45